

FIRE RISK ASSESSMENT

Date: 04/04/2018
Address: Ashleigh Glegg House Grosvenor Rd Seaford
Postcode: BN25 2BW



activefiremanagement.co.uk

Property Ref: SHC 01



**Active Fire
Management**

FIRE RISK ASSESSMENT



Full Property Name:	Sussex Housing and Care
Full Property Address:	Ashleigh Glegg House Grosvenor Rd Seaford BN25 2BW
Date of Fire Risk Assessment:	04/04/2018
Name of Fire Risk Assessor:	Mark Crowter GIFireE
Overall Risk Level of Property:	LOW (3)

FIRE RISK ASSESSMENT		 activefiremanagement.co.uk
Date:	04/04/2018	
Address:	Ashleigh Glegg House Grosvenor Rd Seaford	
Postcode:	BN25 2BW	Property Ref: SHC 01

SECTION A STATEMENT OF FIRE RISK ASSESSMENT

Active Fire Management Ltd has conducted this comprehensive Fire Risk Assessment to assist the Responsible Person in complying with The Regulatory Reform (Fire Safety) Order 2005 in meeting the specific requirements of our client. The Assessment is a systematic evaluation of the premises identifying hazards, potential hazards and persons at risk and determining the likelihood (risk) that such hazards will cause harm. The Assessment we have provided should not be a one off procedure but a dynamic, live process. The Responsible Person is required to have this Assessment constantly reviewed and adjusted if necessary to meet any changing circumstances – Article 9 (3). This Fire Risk Assessment has been conducted using a five-step Fire Risk Assessment process as recommended by HM Government Guides, Employer’s Guides and the Health and Safety Executive. The recommendations of Publicly Available Document 79:2005, Fire Risk Assessment, Guidance and Methodology (PAS 79) have also been considered and it is considered to satisfy the recommendations of the document. This Fire Risk Assessment is made under the requirements of the Regulatory Reform (Fire Safety) Order 2005.

Where appropriate and necessary the assessment included the consideration of sections 1-6, 8, 9, and 11 of the Dangerous Substances and Explosive Atmospheres Regulations 2002 (DSEAR) and other legislation relevant to the premises. The scope of this Fire Risk Assessment does not include roof void space areas.

The Fire Risk Assessment should be available for inspection or validation by any authorised person and should be reviewed:

- Following a change of work practice
- Following a significant change of staffing level
- Following any structural or material change to the premises or its usage
- Following any change in the fire precautions in the premises
- Following any near miss or fire incident
- At recommended intervals of no more than twelve months

The hazards and/or risks identified (if any) in each section of this document increase the risk to life and/or property safety in and around the areas assessed. The additional controls, recommendations and actions given for each section in the action plan/summary section of the document should be dealt with accordingly to bring the assessed areas up to the required standard to reduce the risk to a level which is acceptable in the circumstances. Additionally, in accordance with The Regulatory Reform (Fire Safety) Order 2005, responsible persons must, among other things, ‘provide his employees with comprehensive and relevant information on the risks to them identified by the risk assessment, the preventative and protective measures taken and the procedures and measures, which are in place for serious and imminent danger. Before employing a child, the responsible person must, provide the parents of the child, among other things, with comprehensive and relevant information on the risks to that child identified by the risk assessment, the preventative and protected measures taken and the procedures and measures, which are in place for serious and imminent danger.

This Fire Risk Assessment contains factual information as per the observations, notes and records of the qualified fire risk assessor who completed the site visit and assessment. None of the observations and comments may be changed following the issue of this assessment without the prior consultation with the fire risk assessor. Active Fire Management Ltd will keep a copy of this document for 05 years. Active Fire Management Ltd will provide any additional feedback on comments raised in this report for up to 12 months after the fire risk assessment date noted on this document. In some cases Active Fire Management Ltd may not be able to provide further comments without a re-visit.

The responsible person must also co-operate with other relevant responsible persons (sharing the same occupancy) and inform them of relevant risks in their undertaking. This is Type 1 fire risk assessment (non-destructive/non-intrusive). It is the basic fire risk assessment required for the purpose of satisfying the Fire Safety Order and the inspection of the building is non-destructive.

FIRE RISK ASSESSMENT		 activefiremanagement.co.uk
Date:	04/04/2018	
Address:	Ashleigh Glegg House Grosvenor Rd Seaford	
Postcode:	BN25 2BW	
		Property Ref: SHC 01

SECTION B FIRE RISK ASSESSMENT

SECTION 1 GENERAL		
1.1	DESCRIPTION OF PROPERTY	
REF	DETAILS	
1.1.1	Occupancy/Use:	Sheltered housing
1.1.2	General Description	<p>Ashleigh Glegg House is a building of mainly brick, timber and concrete construction. The building consists of a communal part and flats. The communal part has an office, laundry, kitchenette, lounge and service cupboards. The boiler room is accessed externally. The communal area has two exits. There are 5 separate staircases to the flats and they are arranged as follows –</p> <p>Block 1. Flats 1-5 Block 2. Flats 6-11 Block 3. Flats 13-16 Block 4. Flats 17-22 Block 5 Flats 25-26.</p> <p>Key fire safety features in the building include BS5839 fire alarm and BS5266 emergency lighting.</p>
1.1.3	Number of storeys including basement floors	2
1.1.4	Number of storeys included in the risk assessment	2
1.1.5	Was access gained to any of the flats if applicable to ascertain fire detection means?	Yes. Flat 11.
1.1.6	Responsible Person	Sussex Housing and Care
1.1.7	Name of Responsible Person at Site for Fire Safety	Sussex Housing and Care
1.1.8	Details of Fire Risk Assessor accompanied or met by member of staff (name & position)	Mark Crowter Accompanied by Fiona Williamson.
1.2	USE OF PREMISES	
REF	DETAILS	
1.2.1	Description of Use	Sheltered housing
1.3	OCCUPIERS OF BUILDING	
REF	DETAILS	
1.3.1	Information on Occupants in remote areas	None
1.3.2	Any history of fires in the building	None

FIRE RISK ASSESSMENT

Date: 04/04/2018
 Address: Ashleigh Glegg House Grosvenor Rd Seaford
 Postcode: BN25 2BW



activefiremanagement.co.uk

Property Ref: SHC 01

1.4		FIRE RISK ASSESSMENT			
REF	DETAILS				
1.4.1	Date of Fire Risk Assessment	04/04/2018			
1.4.2	Name of Fire Risk Assessor	Mark Crowter GIFireE			
1.4.3	Risk Level of Property	LOW (3)			
1.4.4	Next Suggested Review Date	04/04/2019			
1.5		CUSTOMER SPECIFIC			
REF	DETAILS	YES	NO	N/A	Not Known
1.5.1	What is the evacuation policy for this property?	SIMULTANEOUS			
1.5.2	Is the evacuation policy deemed as suitable?	X			
1.5.3	When is the next fire risk assessment due in accordance with customer policy?	N/A			
1.5.4	Is this period of time deemed to be suitable?			X	
	If NO state recommendation in action plan and enter date of next recommended fire risk assessment is different to customer policy	NOT APPLICABLE			

FIRE RISK ASSESSMENT

Date: 04/04/2018
 Address: Ashleigh Glegg House Grosvenor Rd Seaford
 Postcode: BN25 2BW



activefiremanagement.co.uk

Property Ref: SHC 01

SECTION 2 FIRE HAZARDS & IGNITION SOURCES

2.1 ELECTRICAL SOURCES OF IGNITION					
REF	DETAILS	YES	NO	N/A	Not Known
2.1.1	Are electrical installations periodically tested?	X			
2.1.2	Is there managerial control of personal electrical items?	X			
2.1.3	Are electrical adaptors or extension leads used safely?	X			
2.1.4	Are electrical cables routed so as to avoid physical damage?	X			
2.1.5	Is lightning protection provided for the building?			X	
2.2 HEATING					
REF	DETAILS	YES	NO	N/A	Not Known
2.2.1	Are mains gas supplies connected?	X			
2.2.2	Are fixed heating installations, gas appliances and boilers subject to regular maintenance by competent contractors?	X			
2.3 COOKING					
REF	DETAILS	YES	NO	N/A	Not Known
2.3.1	Are shared cooking facilities available?	X			
2.3.2	Are cleaning certificates provided/available?			X	
2.4 ARSON					
REF	DETAILS	YES	NO	N/A	Not Known
2.4.1	Is external refuse managed adequately?	X			
2.4.2	Are suitable external security arrangements in place?	X			
2.4.3	Is the building safe from arson, no vulnerability noted?	X			

FIRE RISK ASSESSMENT

Date: 04/04/2018

Address: Ashleigh Glegg House Grosvenor Rd Seaford

Postcode: BN25 2BW



activefiremanagement.co.uk

Property Ref: SHC 01

2.5 STORAGE & HOUSE KEEPING					
REF	DETAILS	YES	NO	N/A	Not Known
2.5.1	Are only small /normal amounts of combustible storage kept in the premises?	X			
2.5.2	Is there avoidance of large or excessive fire loading?	X			
2.5.3	Are storage arrangements adequate?	X			
2.5.4	Are the premises free of highly flammable materials?	X			
	If so are storage arrangements adequate?			X	
2.5.5	Are the premises free of hazardous materials?	X			
	If so are storage arrangements adequate?			X	
2.5.6	Is general housekeeping satisfactory?	X			
2.5.7	Are significant ignition sources separated from combustible or highly flammable materials?	X			
2.5.8	Is the use of highly flammable materials minimised?	X			
2.6 BUILDING WORK & OUTSIDE CONTRACTORS					
REF	DETAILS	YES	NO	N/A	Not Known
2.6.1	At the time of the risk assessment, was the property free of any building work being carried out?	X			
	If NO: Were there any unusual hazards or ignition sources as a result of the building work?			X	
2.6.2	Are any fire safety conditions imposed on contractors?				X
2.6.3	Is there a permit to work/ hot work permits scheme?				X

FIRE RISK ASSESSMENT

Date: 04/04/2018

Address: Ashleigh Glegg House Grosvenor Rd Seaford

Postcode: BN25 2BW



activefiremanagement.co.uk

Property Ref: SHC 01

**SECTION 3
MEANS OF ESCAPE**

3.1 MEANS OF ESCAPE					
REF	DETAILS	YES	NO	N/A	Not Known
3.1.1	Are there adequate numbers of final exit doors?	X			
3.1.2	Are all fire exits immediately open able without use of key?	X			
3.1.3	Are electronic security locks fitted to exit doors on escape routes?		X		
	If YES are they appropriately and safely fitted and maintained?			X	
3.1.4	Do fire exits open in the direction of escape?	X			
3.1.5	Is adequate artificial illumination provided if required?	X			
3.1.6	Are the alternative exit route/s provided with appropriate fire exit signage?	X			
3.1.7	Were fire exit or escape routes noted as satisfactory?	X			
3.1.8	Are the alternative means of escape acceptable?	X			
3.2 PROTECTION OF INTERNAL ESCAPE ROUTES & STRUCTURAL INTEGRITY					
REF	DETAILS	YES	NO	N/A	Not Known
3.2.1	Is the property adequately protected of dead end exit routes?			X	
3.2.2	Are floor surfaces, stairs and handrails etc, safe?	X			
3.2.3	Are exit routes adequately clear of storage & obstructions?	X			
3.2.4	Are existing fire doors fitted with smoke seals, intumescent strips and door closers?	X			
3.2.5	Are fire doors maintained closed and not maintained open by irregular means?	X			
3.2.6	Are service shafts between floors adequately fire stopped?	X			
3.2.7	Are doors to service riser shafts to suitable fire resisting standard?	X			
3.2.8	Is compartmentation considered of a reasonable standard?	X			
3.2.9	Are disabled refuges provided?			X	
3.2.10	If so, are they adequate and provided with appropriate communications and signs?			X	
3.2.11	If so are they considered safe and adequate?			X	
3.2.12	Is the property free of any obvious or apparent risk of fire spread from adjoining or adjacent buildings?	X			
3.2.13	Does the external façade(s) of the premises appear to be of a material that may provide protection against extensive fire spread?	X			

FIRE RISK ASSESSMENT

Date: 04/04/2018

Address: Ashleigh Glegg House Grosvenor Rd Seaford

Postcode: BN25 2BW



activefiremanagement.co.uk

Property Ref: SHC 01

3.3 EXTERNAL EXIT ROUTES					
REF	DETAILS	YES	NO	N/A	Not Known
3.3.1	Do external exit routes lead to a place of final safety?	X			
3.3.2	Are external exit routes even, illuminated, and without obstructions or trip hazards?	X			
3.3.3	Are external staircases, balconies and gangways properly and adequately protected from fire in the parent or adjacent occupancy?	X			
3.3.4	Are external exit routes clear of obstructions, storage, refuse?	X			
3.3.5	Are external exit routes considered satisfactory?	X			

FIRE RISK ASSESSMENT

Date: 04/04/2018

Address: Ashleigh Glegg House Grosvenor Rd Seaford

Postcode: BN25 2BW



activefiremanagement.co.uk

Property Ref: SHC 01

**SECTION 4
EMERGENCY LIGHTING**

4.1	DESCRIPTION				
SELF-CONTAINED UNITS					
4.2	MAINTENANCE & RECORDS				
REF	DETAILS	YES	NO	N/A	Not Known
4.2.1	Is the emergency lighting serviced to comply with the current British Standard 5266?	X			
4.2.2	Is the emergency lighting system in good physical condition?	X			
4.2.3	Are occupants free from risk of emergency lighting deficiencies?	X			

FIRE RISK ASSESSMENT

Date: 04/04/2018

Address: Ashleigh Glegg House Grosvenor Rd Seaford

Postcode: BN25 2BW



activefiremanagement.co.uk

Property Ref: SHC 01

**SECTION 5
SIGNS & NOTICES**

5.1 SIGNS & NOTICES					
REF	DETAILS	YES	NO	N/A	Not Known
5.1.1	Are signs and notices sufficient	X			
	If NO; are the deficiencies serious enough to put occupiers at risk?			X	

FIRE RISK ASSESSMENT

Date: 04/04/2018

Address: Ashleigh Glegg House Grosvenor Rd Seaford

Postcode: BN25 2BW



activefiremanagement.co.uk

Property Ref: SHC 01

**SECTION 6
FIRE ALARM & FIRE WARNING ARRANGEMENTS**

6.1 FIRE ALARM & FIRE WARNING ARRANGEMENTS.					
REF	DETAILS	YES	NO	N/A	Not Known
	Is automatic detection provided?	X			
6.1.1	If YES state where?	THROUGHOUT			
	If partial, indicate areas where provided?	N/A			
6.1.2	Does the system appear to conform to British Standard 5839 part 1? (As far as can be assessed during the inspection)	X			
6.1.3	When was the date of the last service (system)?	29/03/2018			
6.1.4	Are service records up-to-date(system)?	X			
6.1.5	Are there sufficient and suitable fire alarm call points located within the premises?	X			
6.1.6	Are all alarm call points clearly visible, unobstructed and fitted with appropriate fire action signage where required?	X			
6.1.7	Are weekly tests undertaken using a different call point each week with the results recorded in the fire log book.	X			
6.1.8	Are occupants at risk from fire alarm deficiencies?		X		
6.1.9	Does the system in the resident's room/flat comply to BS 5839 part 6 (As far as can be assessed visually during the inspection)	X			

FIRE RISK ASSESSMENT

Date: 04/04/2018
 Address: Ashleigh Glegg House Grosvenor Rd Seaford
 Postcode: BN25 2BW



activefiremanagement.co.uk

Property Ref: SHC 01

SECTION 7 FIXED AND PORTABLE FIRE EXTINGUISHING EQUIPMENT AND INSTALLATIONS

7.1 FIRE FIGHTING EQUIPMENT & INSTALLATIONS					
REF	DETAILS	YES	NO	N/A	Not Known
7.1.1	Are fire extinguishers required to the common areas at this site?		X		
7.1.2	Are fire extinguishers correctly sited and correctly identified by signage?		X		
7.1.3	Date of last service?	29/03/2018			
OTHER FIXED FIRE INSTALLATION & EQUIPMENT					
<i>Provide a description of any other type of fixed firefighting installation provided here (i.e. sprinkler systems misting systems gas suppression system). Including purpose of the system if known.</i>		N/A			
7.1.4	Are the fire installations and equipment periodically inspected, tested and maintained?			X	
7.1.5	Are there records confirming the testing and maintenance available for inspection or use?			X	
7.1.6	Are staff aware of the location of the fixed installations, and what procedures should be followed on their activation?			X	

FIRE RISK ASSESSMENT

Date: 04/04/2018
Address: Ashleigh Glegg House Grosvenor Rd Seaford
Postcode: BN25 2BW



activefiremanagement.co.uk

Property Ref: SHC 01

**SECTION 8
MANAGEMENT OF FIRE SAFETY**

8.1 FIRE ROUTINE & EMERGENCY PLAN					
REF	DETAILS	YES	NO	N/A	Not Known
8.1.1	Is there an Established fire routine and emergency plan?	X			
8.1.2	Are all necessary issues, included in the plan?	X			
8.1.3	Is ongoing staff training appropriate?			X	
8.1.4	Are there a suitable number of fire wardens?			X	
8.1.5	What would be the minimum number of fire wardens at this site?			X	
8.2 RECORD KEEPING					
REF	DETAILS	YES	NO	N/A	Not Known
8.2.1	Is a dedicated fire logbook maintained on site?	X			
8.2.2	Are all appropriate records maintained?	X			

FIRE RISK ASSESSMENT

Date: 04/04/2018

Address: Ashleigh Glegg House Grosvenor Rd Seaford

Postcode: BN25 2BW



activefiremanagement.co.uk

Property Ref: SHC 01

**SECTION 9
ACCESS FOR FIRE FIGHTING & FIRE FIGHTER SAFETY**

9.1	ACCESS				
REF	DETAILS	YES	NO	N/A	Not Known
9.1.1	Is access for the fire service satisfactory?	X			
9.1.2	Is staircase and corridor ventilation satisfactory?	X			

FIRE RISK ASSESSMENT

Date: 04/04/2018
Address: Ashleigh Glegg House Grosvenor Rd Seaford
Postcode: BN25 2BW



activefiremanagement.co.uk

Property Ref: SHC 01

SECTION 10 PHOTOGRAPHS



Photo 1

There is a conventional Fire Alarm System installed to comply with British Standard 5839 part 1. The control panel is positioned in the entrance lobby and provides an evacuation system within the premises. It utilises Sounders as the audible means of alarm. Manual call points supplement automatic fire detectors and are positioned so that no person has to travel more than 45 meters to activate a call point. The Control Panel indicates by use of red LED's the zone of origin of the activation.

There is an indication of the zoning arrangement within the building adjacent to the control panel.



Photo 2

Fire extinguishers are located in the staircases.

It is not considered necessary to provide fire extinguishers in the common parts of flats. Such equipment should only be used by those trained in its use. It is not considered appropriate or practicable for residents in a block of flats to receive such training. In addition, if a fire occurs in a flat, the provision of fire extinguishing appliances in the common parts might encourage the occupants of the flat to enter the common parts to obtain an appliance and return to their flat to fight the fire. Such a procedure is inappropriate.



Photo 3

The carbon dioxide extinguisher located in the communal lounge area is not on a bracket.

FIRE RISK ASSESSMENT

Date: 04/04/2018

Address: Ashleigh Glegg House Grosvenor Rd Seaford

Postcode: BN25 2BW



activefiremanagement.co.uk

Property Ref: SHC 01

SECTION C ACTION PLAN FINDINGS, RECOMMENDATIONS AND GENERAL ADVICE

EXPLANATION OF GRADINGS

The risk management process applied to this report involves the systematic identification of hazards, the assessment of resulting risks and the subsequent management of these risks through control and elimination.

Thereafter a judgment is made to best evaluate a severity (numerical score 1-3) best illustrating the current status for each hazard detailed within this report using the following categories: **People**, **Assets**, **Environment** and **Reputation**.

On the award of a numerical score under the heading severity, this score is then multiplied against the most appropriate likelihood rating of either unlikely, possible or very likely. Thereafter a total score is categorised into an overall risk rating.

Overall risk ratings (see conversion table) are thereafter either High (1), Medium (2) or Low (3). Each of these headings generates a priority weighting (1-3) and depending on the rating this illustrates a compliance timescale (a timescale in which the works should be successfully completed/controlled).

The overall outcome from the conversion table is also recorded and transferred to the Action Plan in this section of the report.

SEVERITY

	PEOPLE	ASSETS	ENVIRONMENTAL	REPUTATION
3	Fatalities	Major Damage	Long Term Harm	Considerable Impact
2	Major Injury	Localised Damage	Short Term Harm	Localised Impact
1	Lost Time Injury	Minor Damage	Low Impact/Little Harm	Limited Impact

FIRE RISK ASSESSMENT

Date: 04/04/2018
 Address: Ashleigh Glegg House Grosvenor Rd Seaford
 Postcode: BN25 2BW



activefiremanagement.co.uk

Property Ref: SHC 01

LIKELIHOOD

Score from Severity Chart ↓	UNLIKELY	POSSIBLE	VERY LIKELY
	Extremely unlikely to occur	Likely to occur some time	Regular or continuous occurrence
	1	2	3
3			HIGH RISK
2		MEDIUM RISK	
1	LOW RISK		

CONVERSION TABLE

OVERALL RISK RATING	PRIORITY	
HIGH RISK	1	Serious Hazard or Deficiency requiring immediate action
MEDIUM RISK	2	Hazard or Deficiency requiring remedial action as soon reasonably feasible
LOW RISK	3	Recommendation for overall fire safety management based on observations or findings
	ADVICE	General advice to be considered in the interests of fire safety

FIRE RISK ASSESSMENT

Date: 04/04/2018

Address: Ashleigh Glegg House Grosvenor Rd Seaford

Postcode: BN25 2BW



activefiremanagement.co.uk

Property Ref: SHC 01

SIGNIFICANT FINDINGS & RECOMMENDATIONS

Relevant to Section 1 of the Fire Risk Assessment

COMPLETED BY ACTIVE FIRE MANAGEMENT

FOR CUSTOMER USE ONLY

REF	SIGNIFICANT FINDINGS	RECOMMENDATIONS	PRIORITY	COMPLETION DATE	COMMENTS	SIGN OFF
	Nil					

ANY OTHER ADDITIONAL CONSIDERATIONS & INFORMATION

relevant to Section 1 of the Fire Risk Assessment

(The following information is provided as guidance & information purposes in the interest of Fire Safety)

FOR CUSTOMER USE ONLY

1.5.1	A simultaneous evacuation policy is in place for this building. Upon the actuation of the fire alarm, all persons will evacuate the building.	
-------	---	--

FIRE RISK ASSESSMENT

Date: 04/04/2018

Address: Ashleigh Glegg House Grosvenor Rd Seaford

Postcode: BN25 2BW



activefiremanagement.co.uk

Property Ref: SHC 01

SIGNIFICANT FINDINGS & RECOMMENDATIONS

Relevant to Section 2 of the Fire Risk Assessment

COMPLETED BY ACTIVE FIRE MANAGEMENT

FOR CUSTOMER USE ONLY

REF	SIGNIFICANT FINDINGS	RECOMMENDATIONS	PRIORITY	COMPLETION DATE	COMMENTS	SIGN OFF
2.6.2 2.6.3	It is not known if safety conditions are imposed on contractors.	It is recommended that any hot works should be subject to a permit-to-work scheme. The use of a hot work permit is appropriate in circumstances where work will involve flames or sparks, where flammable materials are close by and when work is to be completed in environments where such activities are not normally carried out.	3			

ANY OTHER ADDITIONAL CONSIDERATIONS & INFORMATION

relevant to Section 2 of the Fire Risk Assessment

(The following information is provided as guidance & information purposes in the interest of Fire Safety)

FOR CUSTOMER USE ONLY

2.1.1	Mains electrical installation has been tested in accordance with BS7671 5 yearly test. Next due 25/11/2018.	
2.3.1	Communal domestic type kitchen. All appliances have been PAT tested.	

FIRE RISK ASSESSMENT

Date: 04/04/2018

Address: Ashleigh Glegg House Grosvenor Rd Seaford

Postcode: BN25 2BW



activefiremanagement.co.uk

Property Ref: SHC 01

SIGNIFICANT FINDINGS & RECOMMENDATIONS

Relevant to Section 3 of the Fire Risk Assessment

COMPLETED BY ACTIVE FIRE MANAGEMENT

FOR CUSTOMER USE ONLY

REF	SIGNIFICANT FINDINGS	RECOMMENDATIONS	PRIORITY	COMPLETION DATE	COMMENTS	SIGN OFF
	Nil					

ANY OTHER ADDITIONAL CONSIDERATIONS & INFORMATION

relevant to Section 3 of the Fire Risk Assessment

(The following information is provided as guidance & information purposes in the interest of Fire Safety)

FOR CUSTOMER USE ONLY

3.2.4	Access was available to Flat 11. The entrance door is an FD30s standard self-closing fire door, complete with smoke seals and intumescent strips. The front faces of the other flat entrance doors were examined and they were all in good condition with no damage.	
-------	--	--

FIRE RISK ASSESSMENT

Date: 04/04/2018

Address: Ashleigh Glegg House Grosvenor Rd Seaford

Postcode: BN25 2BW



activefiremanagement.co.uk

Property Ref: SHC 01

SIGNIFICANT FINDINGS & RECOMMENDATIONS

Relevant to Section 4 of the Fire Risk Assessment

COMPLETED BY ACTIVE FIRE MANAGEMENT

FOR CUSTOMER USE ONLY

REF	SIGNIFICANT FINDINGS	RECOMMENDATIONS	PRIORITY	COMPLETION DATE	COMMENTS	SIGN OFF
	Nil					

ANY OTHER ADDITIONAL CONSIDERATIONS & INFORMATION

relevant to Section 4 of the Fire Risk Assessment

(The following information is provided as guidance & information purposes in the interest of Fire Safety)

FOR CUSTOMER USE ONLY

4.1	Entries have been made in the system log-book confirming regular maintenance is being undertaken as recommended within BS: 5266.	
-----	--	--

FIRE RISK ASSESSMENT

Date: 04/04/2018

Address: Ashleigh Glegg House Grosvenor Rd Seaford

Postcode: BN25 2BW



activefiremanagement.co.uk

Property Ref: SHC 01

SIGNIFICANT FINDINGS & RECOMMENDATIONS

Relevant to Section 5 of the Fire Risk Assessment

COMPLETED BY ACTIVE FIRE MANAGEMENT

FOR CUSTOMER USE ONLY

REF	SIGNIFICANT FINDINGS	RECOMMENDATIONS	PRIORITY	COMPLETION DATE	COMMENTS	SIGN OFF
	Nil					

ANY OTHER ADDITIONAL CONSIDERATIONS & INFORMATION

relevant to Section 5 of the Fire Risk Assessment

(The following information is provided as guidance & information purposes in the interest of Fire Safety)

FOR CUSTOMER USE ONLY

5.1	<p>Photo-luminescent signage is installed throughout the escape routes, in order that a path to the open air is indicated, in a clear and unambiguous manner.</p> <p>All doors which provide smoke compartmentation have a "Fire Door Keep Closed" Sign on both sides of the door.</p> <p>All doors which are to be kept restricted from general access have a "Fire Door Keep Locked" Sign on the outer (Public) side of the door.</p> <p>Fire Action Notices are in place.</p>	
-----	--	--

FIRE RISK ASSESSMENT

Date: 04/04/2018

Address: Ashleigh Glegg House Grosvenor Rd Seaford

Postcode: BN25 2BW



activefiremanagement.co.uk

Property Ref: SHC 01

SIGNIFICANT FINDINGS & RECOMMENDATIONS

Relevant to Section 6 of the Fire Risk Assessment

COMPLETED BY ACTIVE FIRE MANAGEMENT

FOR CUSTOMER USE ONLY

REF	SIGNIFICANT FINDINGS	RECOMMENDATIONS	PRIORITY	COMPLETION DATE	COMMENTS	SIGN OFF
	Nil					

ANY OTHER ADDITIONAL CONSIDERATIONS & INFORMATION

relevant to Section 6 of the Fire Risk Assessment

(The following information is provided as guidance & information purposes in the interest of Fire Safety)

FOR CUSTOMER USE ONLY

6.1.2	<p>There is a conventional Fire Alarm System installed to comply with British Standard 5839 part 1. The control panel is positioned in the entrance lobby and provides an evacuation system within the premises. It utilises Sounders as the audible means of alarm. Manual call points supplement automatic fire detectors and are positioned so that no person has to travel more than 45 meters to activate a call point. The Control Panel indicates by use of red LED's the zone of origin of the activation.</p> <p>There is an indication of the zoning arrangement within the building adjacent to the control panel.</p> <p>Photo 1</p>	
6.1.9	Access was available to Flat 11. The flat is fitted with hard-wired automatic fire detection.	

FIRE RISK ASSESSMENT

Date: 04/04/2018

Address: Ashleigh Glegg House Grosvenor Rd Seaford

Postcode: BN25 2BW



activefiremanagement.co.uk

Property Ref: SHC 01

SIGNIFICANT FINDINGS & RECOMMENDATIONS
Relevant to Section 7 of the Fire Risk Assessment

COMPLETED BY ACTIVE FIRE MANAGEMENT

FOR CUSTOMER USE ONLY

REF	SIGNIFICANT FINDINGS	RECOMMENDATIONS	PRIORITY	COMPLETION DATE	COMMENTS	SIGN OFF
7.1.1	<p>Fire extinguishers are located in the staircases.</p> <p>It is not considered necessary to provide fire extinguishers in the common parts of flats. Such equipment should only be used by those trained in its use. It is not considered appropriate or practicable for residents in a block of flats to receive such training. In addition, if a fire occurs in a flat, the provision of fire extinguishing appliances in the common parts might encourage the occupants of the flat to enter the common parts to obtain an appliance and return to their flat to fight the fire. Such a procedure is inappropriate.</p> <p>Photo 2</p>	It is recommended that the Fire extinguishers, which are located in the staircases, are removed.	2			
7.1.2	<p>The carbon dioxide extinguisher located in the communal lounge area is not on a bracket.</p> <p>Photo 3</p>	Extinguishers must be stored on a bracket or in a purpose built floor stand.	3			

FIRE RISK ASSESSMENT

Date: 04/04/2018

Address: Ashleigh Glegg House Grosvenor Rd Seaford

Postcode: BN25 2BW

activefiremanagement.co.uk

Property Ref: SHC 01

ANY OTHER ADDITIONAL CONSIDERATIONS & INFORMATION

relevant to Section 7 of the Fire Risk Assessment

(The following information is provided as guidance & information purposes in the interest of Fire Safety)

FOR CUSTOMER USE ONLY

7.1.1 Nil

FIRE RISK ASSESSMENT

Date: 04/04/2018

Address: Ashleigh Glegg House Grosvenor Rd Seaford

Postcode: BN25 2BW



activefiremanagement.co.uk

Property Ref: SHC 01

SIGNIFICANT FINDINGS & RECOMMENDATIONS

Relevant to Section 8 of the Fire Risk Assessment

COMPLETED BY ACTIVE FIRE MANAGEMENT

FOR CUSTOMER USE ONLY

REF	SIGNIFICANT FINDINGS	RECOMMENDATIONS	PRIORITY	COMPLETION DATE	COMMENTS	SIGN OFF
	Nil					

ANY OTHER ADDITIONAL CONSIDERATIONS & INFORMATION

relevant to Section 8 of the Fire Risk Assessment

(The following information is provided as guidance & information purposes in the interest of Fire Safety)

FOR CUSTOMER USE ONLY

8.2.1	Records of testing and maintenance are kept electronically.	
8.2.2		

FIRE RISK ASSESSMENT

Date: 04/04/2018

Address: Ashleigh Glegg House Grosvenor Rd Seaford

Postcode: BN25 2BW



activefiremanagement.co.uk

Property Ref: SHC 01

SIGNIFICANT FINDINGS & RECOMMENDATIONS

Relevant to Section 9 of the Fire Risk Assessment

COMPLETED BY ACTIVE FIRE MANAGEMENT

FOR CUSTOMER USE ONLY

REF	SIGNIFICANT FINDINGS	RECOMMENDATIONS	PRIORITY	COMPLETION DATE	COMMENTS	SIGN OFF
	Nil		-			

ANY OTHER ADDITIONAL CONSIDERATIONS & INFORMATION

relevant to Section 9 of the Fire Risk Assessment

(The following information is provided as guidance & information purposes in the interest of Fire Safety)

FOR CUSTOMER USE ONLY

	Nil	
--	-----	--

END