

**FIRE RISK ASSESSMENT**

Date: 22/06/2018  
Address: The Cedars, Cedars Gardens, Withdene, Brighton  
Postcode: BN1 6YS

**activefiremanagement.co.uk**

Property Ref: SHC 05

**Active Fire  
Management**

# FIRE RISK ASSESSMENT



<b>Full Property Name:</b>	The Cedars
<b>Full Property Address:</b>	Cedars Gardens, Withdene, Brighton BN1 6YS
<b>Date of Fire Risk Assessment:</b>	22/06/2018
<b>Name of Fire Risk Assessor:</b>	Mark Crowter GIFireE
<b>Overall Risk Level of Property:</b>	LOW (3)

<b>FIRE RISK ASSESSMENT</b>		 <b>activefiremanagement.co.uk</b>
Date:	22/06/2018	
Address:	The Cedars, Cedars Gardens, Withdene, Brighton	
Postcode:	BN1 6YS	Property Ref: SHC 05

## SECTION A STATEMENT OF FIRE RISK ASSESSMENT

Active Fire Management Ltd has conducted this comprehensive Fire Risk Assessment to assist the Responsible Person in complying with The Regulatory Reform (Fire Safety) Order 2005 in meeting the specific requirements of our client. The Assessment is a systematic evaluation of the premises identifying hazards, potential hazards and persons at risk and determining the likelihood (risk) that such hazards will cause harm. The Assessment we have provided should not be a one off procedure but a dynamic, live process. The Responsible Person is required to have this Assessment constantly reviewed and adjusted if necessary to meet any changing circumstances – Article 9 (3). This Fire Risk Assessment has been conducted using a five-step Fire Risk Assessment process as recommended by HM Government Guides, Employer's Guides and the Health and Safety Executive. The recommendations of Publicly Available Document 79:2005, Fire Risk Assessment, Guidance and Methodology (PAS 79) have also been considered and it is considered to satisfy the recommendations of the document. This Fire Risk Assessment is made under the requirements of the Regulatory Reform (Fire Safety) Order 2005.

Where appropriate and necessary the assessment included the consideration of sections 1-6, 8, 9, and 11 of the Dangerous Substances and Explosive Atmospheres Regulations 2002 (DSEAR) and other legislation relevant to the premises. The scope of this Fire Risk Assessment does not include roof void space areas.

The Fire Risk Assessment should be available for inspection or validation by any authorised person and should be reviewed:

- Following a change of work practice
- Following a significant change of staffing level
- Following any structural or material change to the premises or its usage
- Following any change in the fire precautions in the premises
- Following any near miss or fire incident
- At recommended intervals of no more than twelve months

The hazards and/or risks identified (if any) in each section of this document increase the risk to life and/or property safety in and around the areas assessed. The additional controls, recommendations and actions given for each section in the action plan/summary section of the document should be dealt with accordingly to bring the assessed areas up to the required standard to reduce the risk to a level which is acceptable in the circumstances. Additionally, in accordance with The Regulatory Reform (Fire Safety) Order 2005, responsible persons must, among other things, 'provide his employees with comprehensive and relevant information on the risks to them identified by the risk assessment, the preventative and protective measures taken and the procedures and measures, which are in place for serious and imminent danger. Before employing a child, the responsible person must, provide the parents of the child, among other things, with comprehensive and relevant information on the risks to that child identified by the risk assessment, the preventative and protected measures taken and the procedures and measures, which are in place for serious and imminent danger.

This Fire Risk Assessment contains factual information as per the observations, notes and records of the qualified fire risk assessor who completed the site visit and assessment. None of the observations and comments may be changed following the issue of this assessment without the prior consultation with the fire risk assessor. Active Fire Management Ltd will keep a copy of this document for 05 years. Active Fire Management Ltd will provide any additional feedback on comments raised in this report for up to 12 months after the fire risk assessment date noted on this document. In some cases Active Fire Management Ltd may not be able to provide further comments without a re-visit.

The responsible person must also co-operate with other relevant responsible persons (sharing the same occupancy) and inform them of relevant risks in their undertaking. This is Type 1 fire risk assessment (non-destructive/non-intrusive). It is the basic fire risk assessment required for the purpose of satisfying the Fire Safety Order and the inspection of the building is non-destructive.

**FIRE RISK ASSESSMENT**

Date: 22/06/2018  
 Address: The Cedars, Cedars Gardens, Withdene, Brighton  
 Postcode: BN1 6YS



activefiremanagement.co.uk

Property Ref: SHC 05

## SECTION B FIRE RISK ASSESSMENT

### SECTION 1 GENERAL

1.1	DESCRIPTION OF PROPERTY	
REF	DETAILS	
1.1.1	Occupancy/Use:	Sheltered Accommodation
1.1.2	General Description	<p>The Cedars is a purpose built sheltered scheme comprising 25 self-contained flats. The buildings are of brick and concrete construction with the first floor flats opening onto open deck escape routes. Flats 18-21 have staircases at each end of the open deck escape routes. Flats 22-23, 25-26 and 5-7 have single direction escape routes. Ground floor flats have exits directly to open air. The open balcony design would allow smoke and heat to be mainly dissipated to open air in the event of a fire. The assessment includes the small communal lounge, laundry room and scheme manager's office. The boiler room is accessed externally and the buggy store is located in a purpose built garage.</p> <p>Key fire safety features in the buildings include BS5839 fire alarm system and BS5266 emergency lighting.</p>
1.1.3	Number of storeys including basement floors	2
1.1.4	Number of storeys included in the risk assessment	2
1.1.5	Was access gained to any of the flats if applicable to ascertain fire detection means?	No
1.1.6	Responsible Person	Sussex Housing and Care
1.1.7	Name of Responsible Person at Site for Fire Safety	Sussex Housing and Care
1.1.8	Details of Fire Risk Assessor accompanied or met by member of staff (name & position)	Not Accompanied.
1.2	USE OF PREMISES	
REF	DETAILS	
1.2.1	Description of Use	Sheltered Accommodation
1.3	OCCUPIERS OF BUILDING	
REF	DETAILS	
1.3.1	Information on Occupants	Residents are over 60, independent living.
1.3.2	Any history of fires in the building	None

**FIRE RISK ASSESSMENT**

Date: 22/06/2018  
 Address: The Cedars, Cedars Gardens, Withdene, Brighton  
 Postcode: BN1 6YS



activefiremanagement.co.uk

Property Ref: SHC 05

1.4 FIRE RISK ASSESSMENT					
REF	DETAILS				
1.4.1	Date of Fire Risk Assessment	22/06/2018			
1.4.2	Name of Fire Risk Assessor	Mark Crowter GIFireE			
1.4.3	Risk Level of Property	LOW (3)			
1.4.4	Next Suggested Review Date	22/06/2018			
1.5 CUSTOMER SPECIFIC					
REF	DETAILS	YES	NO	N/A	Not Known
1.5.1	What is the evacuation policy for this property?	<b>SIMULTANEOUS EVACUATION POLICY</b>			
1.5.2	Is the evacuation policy deemed as suitable?	X			
1.5.3	When is the next fire risk assessment due in accordance with customer policy?	N/A			
1.5.4	Is this period of time deemed to be suitable?			X	
	If NO state recommendation in action plan and enter date of next recommended fire risk assessment is different to customer policy	NOT APPLICABLE			

**FIRE RISK ASSESSMENT**

Date: 22/06/2018  
 Address: The Cedars, Cedars Gardens, Withdene, Brighton  
 Postcode: BN1 6YS



activefiremanagement.co.uk

Property Ref: SHC 05

## SECTION 2 FIRE HAZARDS & IGNITION SOURCES

<b>2.1 ELECTRICAL SOURCES OF IGNITION</b>					
<b>REF</b>	<b>DETAILS</b>	<b>YES</b>	<b>NO</b>	<b>N/A</b>	<b>Not Known</b>
2.1.1	Are electrical installations periodically tested?	X			
2.1.2	Is there managerial control of personal electrical items?	X			
2.1.3	Are electrical adaptors or extension leads used safely?	X			
2.1.4	Are electrical cables routed so as to avoid physical damage?	X			
2.1.5	Is lightning protection provided for the building?			X	
<b>2.2 HEATING</b>					
<b>REF</b>	<b>DETAILS</b>	<b>YES</b>	<b>NO</b>	<b>N/A</b>	<b>Not Known</b>
2.2.1	Are mains gas supplies connected?		X		
2.2.2	Are fixed heating installations, gas appliances and boilers subject to regular maintenance by competent contractors?			X	
<b>2.3 COOKING</b>					
<b>REF</b>	<b>DETAILS</b>	<b>YES</b>	<b>NO</b>	<b>N/A</b>	<b>Not Known</b>
2.3.1	Are shared cooking facilities available?	X			
2.3.2	Are cleaning certificates provided/available?			X	
<b>2.4 ARSON</b>					
<b>REF</b>	<b>DETAILS</b>	<b>YES</b>	<b>NO</b>	<b>N/A</b>	<b>Not Known</b>
2.4.1	Is external refuse managed adequately?	X			
2.4.2	Are suitable external security arrangements in place?	X			
2.4.3	Is the building safe from arson, no vulnerability noted?	X			

**FIRE RISK ASSESSMENT**

Date: 22/06/2018

Address: The Cedars, Cedars Gardens, Withdene, Brighton

Postcode: BN1 6YS



activefiremanagement.co.uk

Property Ref: SHC 05

<b>2.5 STORAGE &amp; HOUSE KEEPING</b>					
<b>REF</b>	<b>DETAILS</b>	<b>YES</b>	<b>NO</b>	<b>N/A</b>	<b>Not Known</b>
2.5.1	Are only small /normal amounts of combustible storage kept in the premises?	X			
2.5.2	Is there avoidance of large or excessive fire loading?	X			
2.5.3	Are storage arrangements adequate?	X			
2.5.4	Are the premises free of highly flammable materials?	X			
	If so are storage arrangements adequate?			X	
2.5.5	Are the premises free of hazardous materials?	X			
	If so are storage arrangements adequate?			X	
2.5.6	Is general housekeeping satisfactory?	X			
2.5.7	Are significant ignition sources separated from combustible or highly flammable materials?	X			
2.5.8	Is the use of highly flammable materials minimised?	X			
<b>2.6 BUILDING WORK &amp; OUTSIDE CONTRACTORS</b>					
<b>REF</b>	<b>DETAILS</b>	<b>YES</b>	<b>NO</b>	<b>N/A</b>	<b>Not Known</b>
2.6.1	At the time of the risk assessment, was the property free of any building work being carried out?	X			
	If NO: Were there any unusual hazards or ignition sources as a result of the building work?			X	
2.6.2	Are any fire safety conditions imposed on contractors?				X
2.6.3	Is there a permit to work/ hot work permits scheme?				X

**FIRE RISK ASSESSMENT**

Date: 22/06/2018

Address: The Cedars, Cedars Gardens, Withdene, Brighton

Postcode: BN1 6YS



activefiremanagement.co.uk

Property Ref: SHC 05

**SECTION 3  
MEANS OF ESCAPE**

<b>3.1 MEANS OF ESCAPE</b>					
<b>REF</b>	<b>DETAILS</b>	<b>YES</b>	<b>NO</b>	<b>N/A</b>	<b>Not Known</b>
3.1.1	Are there adequate numbers of final exit doors?	X			
3.1.2	Are all fire exits immediately open able without use of key?	X			
3.1.3	Are electronic security locks fitted to exit doors on escape routes?	X			
	If YES are they appropriately and safely fitted and maintained?	X			
3.1.4	Do fire exits open in the direction of escape?	X			
3.1.5	Is adequate artificial illumination provided if required?	X			
3.1.6	Are the alternative exit route/s provided with appropriate fire exit signage?	X			
3.1.7	Were fire exit or escape routes noted as satisfactory?	X			
3.1.8	Are the alternative means of escape acceptable?	X			
<b>3.2 PROTECTION OF INTERNAL ESCAPE ROUTES &amp; STRUCTURAL INTEGRITY</b>					
<b>REF</b>	<b>DETAILS</b>	<b>YES</b>	<b>NO</b>	<b>N/A</b>	<b>Not Known</b>
3.2.1	Is the property adequately protected of dead end exit routes?			X	
3.2.2	Are floor surfaces, stairs and handrails etc, safe?	X			
3.2.3	Are exit routes adequately clear of storage & obstructions?	X			
3.2.4	Are existing fire doors fitted with smoke seals, intumescent strips and door closers?		X		
3.2.5	Are fire doors maintained closed and not maintained open by irregular means?	X			
3.2.6	Are service shafts between floors adequately fire stopped?	X			
3.2.7	Are doors to service riser shafts to suitable fire resisting standard?	X			
3.2.8	Is compartmentation considered of a reasonable standard?	X			
3.2.9	Are disabled refuges provided?			X	
3.2.10	If so, are they adequate and provided with appropriate communications and signs?			X	
3.2.11	If so are they considered safe and adequate?			X	
3.2.12	Is the property free of any obvious or apparent risk of fire spread from adjoining or adjacent buildings?	X			
3.2.13	Does the external façade(s) of the premises appear to be of a material that may provide protection against extensive fire spread?	X			

**FIRE RISK ASSESSMENT**

Date: 22/06/2018

Address: The Cedars, Cedars Gardens, Withdene, Brighton

Postcode: BN1 6YS



activefiremanagement.co.uk

Property Ref: SHC 05

<b>3.3</b>	<b>EXTERNAL EXIT ROUTES</b>				
<b>REF</b>	<b>DETAILS</b>	<b>YES</b>	<b>NO</b>	<b>N/A</b>	<b>Not Known</b>
3.3.1	Do external exit routes lead to a place of final safety?	X			
3.3.2	Are external exit routes even, illuminated, and without obstructions or trip hazards?	X			
3.3.3	Are external staircases, balconies and gangways properly and adequately protected from fire in the parent or adjacent occupancy?	X			
3.3.4	Are external exit routes clear of obstructions, storage, refuse?	X			
3.3.5	Are external exit routes considered satisfactory?	X			



**FIRE RISK ASSESSMENT**

Date: 22/06/2018  
Address: The Cedars, Cedars Gardens, Withdene, Brighton  
Postcode: BN1 6YS



activefiremanagement.co.uk

Property Ref: SHC 05

**SECTION 4  
EMERGENCY LIGHTING**

4.1	DESCRIPTION				
<b>SELF-CONTAINED UNITS</b>					
4.2	MAINTENANCE & RECORDS				
REF	DETAILS	YES	NO	N/A	Not Known
4.2.1	Is the emergency lighting serviced to comply with the current British Standard 5266?	X			
4.2.2	Is the emergency lighting system in good physical condition?	X			
4.2.3	Are occupants free from risk of emergency lighting deficiencies?	X			

**FIRE RISK ASSESSMENT**

Date: 22/06/2018  
Address: The Cedars, Cedars Gardens, Withdene, Brighton  
Postcode: BN1 6YS



activefiremanagement.co.uk

Property Ref: SHC 05

**SECTION 5  
SIGNS & NOTICES**

5.1		SIGNS & NOTICES			
REF	DETAILS	YES	NO	N/A	Not Known
5.1.1	Are signs and notices sufficient	X			
	If NO; are the deficiencies serious enough to put occupiers at risk?			X	

**FIRE RISK ASSESSMENT**

Date: 22/06/2018

Address: The Cedars, Cedars Gardens, Withdene, Brighton

Postcode: BN1 6YS



activefiremanagement.co.uk

Property Ref: SHC 05

**SECTION 6  
FIRE ALARM & FIRE WARNING ARRANGEMENTS**

<b>6.1 FIRE ALARM &amp; FIRE WARNING ARRANGEMENTS.</b>					
<b>REF</b>	<b>DETAILS</b>	<b>YES</b>	<b>NO</b>	<b>N/A</b>	<b>Not Known</b>
	Is automatic detection provided?	X			
6.1.1	If YES state where?	<b>COMMUNAL ROOMS</b>			
	If partial, indicate areas where provided?	<b>N/A</b>			
6.1.2	Does the system appear to conform to British Standard 5839 part 1? (As far as can be assessed during the inspection)	X			
6.1.3	When was the date of the last service (system)?	<b>20/10/2017</b>			
6.1.4	Are service records up-to-date(system)?	X			
6.1.5	Are there sufficient and suitable fire alarm call points located within the premises?	X			
6.1.6	Are all alarm call points clearly visible, unobstructed and fitted with appropriate fire action signage where required?	X			
6.1.7	Are weekly tests undertaken using a different call point each week with the results recorded in the fire log book.	X			
6.1.8	Are occupants at risk from fire alarm deficiencies?		X		
6.1.9	Does the system in the resident's room/flat comply to BS 5839 part 6 (As far as can be assessed visually during the inspection)	X			

**FIRE RISK ASSESSMENT**

Date: 22/06/2018  
 Address: The Cedars, Cedars Gardens, Withdene, Brighton  
 Postcode: BN1 6YS



activefiremanagement.co.uk

Property Ref: SHC 05

## SECTION 7 FIXED AND PORTABLE FIRE EXTINGUISHING EQUIPMENT AND INSTALLATIONS

7.1 FIRE FIGHTING EQUIPMENT & INSTALLATIONS					
REF	DETAILS	YES	NO	N/A	Not Known
7.1.1	Are fire extinguishers required to the common areas at this site?	X			
7.1.2	Are fire extinguishers correctly sited and correctly identified by signage?		X		
7.1.3	Date of last service?	JULY 2017			
OTHER FIXED FIRE INSTALLATION & EQUIPMENT					
<i>Provide a description of any other type of fixed firefighting installation provided here (i.e. sprinkler systems misting systems gas suppression system). Including purpose of the system if known.</i>		N/A			
7.1.4	Are the fire installations and equipment periodically inspected, tested and maintained?			X	
7.1.5	Are there records confirming the testing and maintenance available for inspection or use?			X	
7.1.6	Are staff aware of the location of the fixed installations, and what procedures should be followed on their activation?			X	

**FIRE RISK ASSESSMENT**

Date: 22/06/2018  
 Address: The Cedars, Cedars Gardens, Withdene, Brighton  
 Postcode: BN1 6YS



activefiremanagement.co.uk

Property Ref: SHC 05

## SECTION 8 MANAGEMENT OF FIRE SAFETY

8.1 FIRE ROUTINE & EMERGENCY PLAN					
REF	DETAILS	YES	NO	N/A	Not Known
8.1.1	Is there an Established fire routine and emergency plan?	X			
8.1.2	Are all necessary issues, included in the plan?	X			
8.1.3	Is ongoing staff training appropriate?	X			
8.1.4	Are there a suitable number of fire wardens?			X	
8.1.5	What would be the minimum number of fire wardens at this site?			X	
8.2 RECORD KEEPING					
REF	DETAILS	YES	NO	N/A	Not Known
8.2.1	Is a dedicated fire logbook maintained on site?	X			
8.2.2	Are all appropriate records maintained?	X			

**FIRE RISK ASSESSMENT**

Date: 22/06/2018

Address: The Cedars, Cedars Gardens, Withdene, Brighton

Postcode: BN1 6YS



activefiremanagement.co.uk

Property Ref: SHC 05

**SECTION 9  
ACCESS FOR FIRE FIGHTING & FIRE FIGHTER SAFETY**

9.1	ACCESS				
REF	DETAILS	YES	NO	N/A	Not Known
9.1.1	Is access for the fire service satisfactory?	X			
9.1.2	Is staircase and corridor ventilation satisfactory?	X			

# FIRE RISK ASSESSMENT

Date: 22/06/2018  
Address: The Cedars, Cedars Gardens, Withdene, Brighton  
Postcode: BN1 6YS



activefiremanagement.co.uk

Property Ref: SHC 05

## SECTION 10 PHOTOGRAPHS



### Photo 1

Mains electrical installation has been tested in accordance with BS7671 5 yearly test. Next due November 2019.



### Photo 2

The fire door to the kitchen is not fitted with a self-closer.



### Photo 3

There is an Addressable Fire Alarm System installed to comply with British Standard 5839 part 1. The control panel provides a simultaneous evacuation system within the premises, utilising Sounders as the audible means of alarm. Manual call points are generally situated at exits and along exit routes, and positioned so that no person has to travel more than 45 meters to activate a call point. There is a call point adjacent to each escape route exit to the premises. Automatic fire detection is provided in the escape routes and adjoining rooms.

At the time of the assessment, the fire alarm panel was showing healthy supply with no faults.

## FIRE RISK ASSESSMENT

Date: 22/06/2018  
Address: The Cedars, Cedars Gardens, Withdene, Brighton  
Postcode: BN1 6YS



activefiremanagement.co.uk

Property Ref: SHC 05



### Photo 4

There is over-provision of fire extinguishers to the open deck escape routes in the residential blocks.



## FIRE RISK ASSESSMENT

Date: 22/06/2018  
Address: The Cedars, Cedars Gardens, Withdene, Brighton  
Postcode: BN1 6YS



activefiremanagement.co.uk

Property Ref: SHC 05

## SECTION C ACTION PLAN FINDINGS, RECOMMENDATIONS AND GENERAL ADVICE

### EXPLANATION OF GRADINGS

The risk management process applied to this report involves the systematic identification of hazards, the assessment of resulting risks and the subsequent management of these risks through control and elimination.

Thereafter a judgment is made to best evaluate a severity (numerical score 1-3) best illustrating the current status for each hazard detailed within this report using the following categories: **People**, **Assets**, **Environment** and **Reputation**.

On the award of a numerical score under the heading severity, this score is then multiplied against the most appropriate likelihood rating of either unlikely, possible or very likely. Thereafter a total score is categorised into an overall risk rating.

Overall risk ratings (see conversion table) are thereafter either High (1), Medium (2) or Low (3). Each of these headings generates a priority weighting (1-3) and depending on the rating this illustrates a compliance timescale (a timescale in which the works should be successfully completed/controlled).

The overall outcome from the conversion table is also recorded and transferred to the Action Plan in this section of the report.

## SEVERITY

	PEOPLE	ASSETS	ENVIRONMENTAL	REPUTATION
3	Fatalities	Major Damage	Long Term Harm	Considerable Impact
2	Major Injury	Localised Damage	Short Term Harm	Localised Impact
1	Lost Time Injury	Minor Damage	Low Impact/Little Harm	Limited Impact

**FIRE RISK ASSESSMENT**

Date: 22/06/2018  
 Address: The Cedars, Cedars Gardens, Withdene, Brighton  
 Postcode: BN1 6YS



activefiremanagement.co.uk

Property Ref: SHC 05

**LIKELIHOOD**

Score from Severity Chart ↓	UNLIKELY	POSSIBLE	VERY LIKELY
	Extremely unlikely to occur	Likely to occur some time	Regular or continuous occurrence
	1	2	3
3			<b>HIGH RISK</b>
2		<b>MEDIUM RISK</b>	
1	<b>LOW RISK</b>		

**CONVERSION TABLE**

OVERALL RISK RATING	PRIORITY	
<b>HIGH RISK</b>	1	Serious Hazard or Deficiency requiring immediate action
<b>MEDIUM RISK</b>	2	Hazard or Deficiency requiring remedial action as soon reasonably feasible
<b>LOW RISK</b>	3	Recommendation for overall fire safety management based on observations or findings
	<b>ADVICE</b>	General advice to be considered in the interests of fire safety

**FIRE RISK ASSESSMENT**

Date: 22/06/2018

Address: The Cedars, Cedars Gardens, Withdene, Brighton

Postcode: BN1 6YS



activefiremanagement.co.uk

Property Ref: SHC 05

**SIGNIFICANT FINDINGS & RECOMMENDATIONS**

Relevant to Section 1 of the Fire Risk Assessment

COMPLETED BY ACTIVE FIRE MANAGEMENT

FOR CUSTOMER USE ONLY

REF	SIGNIFICANT FINDINGS	RECOMMENDATIONS	PRIORITY	COMPLETION DATE	COMMENTS	SIGN OFF
	Nil					

**ANY OTHER ADDITIONAL CONSIDERATIONS & INFORMATION**

relevant to Section 1 of the Fire Risk Assessment

(The following information is provided as guidance &amp; information purposes in the interest of Fire Safety)

FOR CUSTOMER USE ONLY

	Nil	
--	-----	--

**FIRE RISK ASSESSMENT**

Date: 22/06/2018

Address: The Cedars, Cedars Gardens, Withdene, Brighton

Postcode: BN1 6YS



activefiremanagement.co.uk

Property Ref: SHC 05

**SIGNIFICANT FINDINGS & RECOMMENDATIONS**

Relevant to Section 2 of the Fire Risk Assessment

COMPLETED BY ACTIVE FIRE MANAGEMENT

FOR CUSTOMER USE ONLY

REF	SIGNIFICANT FINDINGS	RECOMMENDATIONS	PRIORITY	COMPLETION DATE	COMMENTS	SIGN OFF
2.6.2 2.6.3	It is not known if safety conditions are imposed on contractors.	It is recommended that any hot works should be subject to a permit-to-work scheme. The use of a hot work permit is appropriate in circumstances where work will involve flames or sparks, where flammable materials are close by and when work is to be completed in environments where such activities are not normally carried out.	3			

**FIRE RISK ASSESSMENT**

Date: 22/06/2018

Address: The Cedars, Cedars Gardens, Withdene, Brighton

Postcode: BN1 6YS



activefiremanagement.co.uk

Property Ref: SHC 05

**ANY OTHER ADDITIONAL CONSIDERATIONS & INFORMATION  
relevant to Section 2 of the Fire Risk Assessment****FOR CUSTOMER USE ONLY***(The following information is provided as guidance & information purposes in the interest of Fire Safety)*

2.1.1	Mains electrical installation has been tested in accordance with BS7671 5 yearly test. Next due November 2019. <b>Photo 1</b>	
2.1.2	There is evidence that portable appliance testing (PAT Testing) is undertaken regularly in compliance with the schedule in the Electricity at Work Regulations 1989. Tested 14/12/2017.	
2.3.1	There is a free-standing domestic type cooker provided in the kitchen. The kitchen is supplied with automatic fire detection a CO2 extinguisher and a Fire Blanket. There is no requirement to provide any filters or ductwork for an appliance of this type. The cooker should be tested and maintained by a competent person in good working order. All other appliances, kettle, toaster, etc. have been tested as part of the PAT testing regime for the building.	
2.4	Security from unsolicited entry to the building is satisfactory. Doors on the periphery of the buildings are provided with suitable locking devices and the main entrance door has electronic access control facilities. There was no extraneous fire loading close to the building at the time of the inspection.	
2.5	The exit from the laundry room is directly to open air. Dryer filters are cleaned by the residents; signage is in place to remind them.	
2.5.5	This risk assessment only considers the impact of the use or storage of dangerous substances to the extent necessary to determine the adequacy of the general fire precautions required under the Order to ensure the safety of relevant persons in the event of fire. There are no dangerous substances used or stored in the common parts.	

**FIRE RISK ASSESSMENT**

Date: 22/06/2018

Address: The Cedars, Cedars Gardens, Withdene, Brighton

Postcode: BN1 6YS



activefiremanagement.co.uk

Property Ref: SHC 05

**SIGNIFICANT FINDINGS & RECOMMENDATIONS**

Relevant to Section 3 of the Fire Risk Assessment

COMPLETED BY ACTIVE FIRE MANAGEMENT

FOR CUSTOMER USE ONLY

REF	SIGNIFICANT FINDINGS	RECOMMENDATIONS	PRIORITY	COMPLETION DATE	COMMENTS	SIGN OFF
3.2.4	The fire door to the kitchen is not fitted with a self-closer. <b>Photo 2</b>	The kitchen fire door must be fitted with a self-closer, which conforms to BS EN 1154.	2			

**ANY OTHER ADDITIONAL CONSIDERATIONS & INFORMATION**

relevant to Section 3 of the Fire Risk Assessment

(The following information is provided as guidance &amp; information purposes in the interest of Fire Safety)

FOR CUSTOMER USE ONLY

Nil	
-----	--

**FIRE RISK ASSESSMENT**

Date: 22/06/2018

Address: The Cedars, Cedars Gardens, Withdene, Brighton

Postcode: BN1 6YS



activefiremanagement.co.uk

Property Ref: SHC 05

**SIGNIFICANT FINDINGS & RECOMMENDATIONS**

Relevant to Section 4 of the Fire Risk Assessment

COMPLETED BY ACTIVE FIRE MANAGEMENT

FOR CUSTOMER USE ONLY

REF	SIGNIFICANT FINDINGS	RECOMMENDATIONS	PRIORITY	COMPLETION DATE	COMMENTS	SIGN OFF
	Nil					

**ANY OTHER ADDITIONAL CONSIDERATIONS & INFORMATION**

relevant to Section 4 of the Fire Risk Assessment

(The following information is provided as guidance &amp; information purposes in the interest of Fire Safety)

FOR CUSTOMER USE ONLY

4.1	Self-contained units in place in the internal and external escape routes. Emergency lighting is provided in the common areas to illuminate the escape routes and ensure that Safety signage, fire safety equipment and hazards are visible.					
-----	--	--	--	--	--	--

<b>FIRE RISK ASSESSMENT</b>		 <b>activefiremanagement.co.uk</b>
Date:	22/06/2018	
Address:	The Cedars, Cedars Gardens, Withdene, Brighton	
Postcode:	BN1 6YS	Property Ref: SHC 05

**SIGNIFICANT FINDINGS & RECOMMENDATIONS**  
**Relevant to Section 5 of the Fire Risk Assessment**

**COMPLETED BY ACTIVE FIRE MANAGEMENT**

COMPLETED BY ACTIVE FIRE MANAGEMENT				FOR CUSTOMER USE ONLY		
REF	SIGNIFICANT FINDINGS	RECOMMENDATIONS	PRIORITY	COMPLETION DATE	COMMENTS	SIGN OFF
	Nil					

**ANY OTHER ADDITIONAL CONSIDERATIONS & INFORMATION**  
**relevant to Section 5 of the Fire Risk Assessment**

*(The following information is provided as guidance & information purposes in the interest of Fire Safety)*

ANY OTHER ADDITIONAL CONSIDERATIONS & INFORMATION relevant to Section 5 of the Fire Risk Assessment <i>(The following information is provided as guidance &amp; information purposes in the interest of Fire Safety)</i>		FOR CUSTOMER USE ONLY
5.1	All doors, which provide smoke compartmentation, have a "Fire Door Keep Closed" Sign on both sides of the door. All doors, which are to be kept restricted from general access, have a "Fire Door Keep Locked" Sign on the outer (Public) side of the door.	



**FIRE RISK ASSESSMENT**

Date: 22/06/2018

Address: The Cedars, Cedars Gardens, Withdene, Brighton

Postcode: BN1 6YS



activefiremanagement.co.uk

Property Ref: SHC 05

**SIGNIFICANT FINDINGS & RECOMMENDATIONS**

Relevant to Section 6 of the Fire Risk Assessment

COMPLETED BY ACTIVE FIRE MANAGEMENT

FOR CUSTOMER USE ONLY

REF	SIGNIFICANT FINDINGS	RECOMMENDATIONS	PRIORITY	COMPLETION DATE	COMMENTS	SIGN OFF
	Nil					

**ANY OTHER ADDITIONAL CONSIDERATIONS & INFORMATION**

relevant to Section 6 of the Fire Risk Assessment

(The following information is provided as guidance &amp; information purposes in the interest of Fire Safety)

FOR CUSTOMER USE ONLY

6.1.1	There is an Addressable Fire Alarm System installed to comply with British Standard 5839 part 1. The control panel provides a simultaneous evacuation system within the premises, utilising Sounders as the audible means of alarm. Manual call points are generally situated at exits and along exit routes, and positioned so that no person has to travel more than 45 meters to activate a call point. There is a call point adjacent to each escape route exit to the premises. Automatic fire detection is provided in the escape routes and adjoining rooms. At the time of the assessment, the fire alarm panel was showing healthy supply with no faults. <b>Photo 3</b>	
6.1.9	Access was not available to the individual flats. However, we were informed by some of the residents that the flats are fitted with mains powered automatic fire detection.	
6.1.7	Records of weekly Bell tests are available. Records are kept electronically.	

**FIRE RISK ASSESSMENT**

Date: 22/06/2018

Address: The Cedars, Cedars Gardens, Withdene, Brighton

Postcode: BN1 6YS



activefiremanagement.co.uk

Property Ref: SHC 05

**SIGNIFICANT FINDINGS & RECOMMENDATIONS**

Relevant to Section 7 of the Fire Risk Assessment

COMPLETED BY ACTIVE FIRE MANAGEMENT

FOR CUSTOMER USE ONLY

REF	SIGNIFICANT FINDINGS	RECOMMENDATIONS	PRIORITY	COMPLETION DATE	COMMENTS	SIGN OFF
7.1.2	<p>There is over-provision of fire extinguishers to the open deck escape routes in the residential blocks.</p> <p>It is not considered necessary to provide fire extinguishers in the common parts of flats. Such equipment should only be used by those trained in its use. It is not considered appropriate or practicable for residents in a block of flats to receive such training. In addition, if a fire occurs in a flat, the provision of fire extinguishing appliances in the common parts might encourage the occupants of the flat to enter the common parts to obtain an appliance and return to their flat to fight the fire. Such a procedure is inappropriate.</p> <p><b>Photo 4</b></p>	<p>It is recommended that the fire extinguishers be removed from the open deck escape routes in the residential blocks.</p> <p>The extinguishers located in the lounge, kitchen, laundry room and office should remain.</p>	3			

**ANY OTHER ADDITIONAL CONSIDERATIONS & INFORMATION**

relevant to Section 7 of the Fire Risk Assessment

(The following information is provided as guidance &amp; information purposes in the interest of Fire Safety)

FOR CUSTOMER USE ONLY

Nil	
-----	--

**FIRE RISK ASSESSMENT**

Date: 22/06/2018

Address: The Cedars, Cedars Gardens, Withdene, Brighton

Postcode: BN1 6YS



activefiremanagement.co.uk

Property Ref: SHC 05

**SIGNIFICANT FINDINGS & RECOMMENDATIONS**

Relevant to Section 8 of the Fire Risk Assessment

COMPLETED BY ACTIVE FIRE MANAGEMENT

FOR CUSTOMER USE ONLY

REF	SIGNIFICANT FINDINGS	RECOMMENDATIONS	PRIORITY	COMPLETION DATE	COMMENTS	SIGN OFF
	Nil					

**ANY OTHER ADDITIONAL CONSIDERATIONS & INFORMATION**

relevant to Section 8 of the Fire Risk Assessment

(The following information is provided as guidance &amp; information purposes in the interest of Fire Safety)

FOR CUSTOMER USE ONLY

8.2.1	Records of testing and maintenance are kept electronically.	
8.2.2		

**FIRE RISK ASSESSMENT**

Date: 22/06/2018

Address: The Cedars, Cedars Gardens, Withdene, Brighton

Postcode: BN1 6YS



activefiremanagement.co.uk

Property Ref: SHC 05

**SIGNIFICANT FINDINGS & RECOMMENDATIONS**

Relevant to Section 9 of the Fire Risk Assessment

COMPLETED BY ACTIVE FIRE MANAGEMENT

FOR CUSTOMER USE ONLY

REF	SIGNIFICANT FINDINGS	RECOMMENDATIONS	PRIORITY	COMPLETION DATE	COMMENTS	SIGN OFF
	Nil		-			

**ANY OTHER ADDITIONAL CONSIDERATIONS & INFORMATION**

relevant to Section 9 of the Fire Risk Assessment

(The following information is provided as guidance &amp; information purposes in the interest of Fire Safety)

FOR CUSTOMER USE ONLY

	Nil	
--	-----	--

**END**